



NATIONAL OPTICAL ASTRONOMY OBSERVATORY

950 N. Cherry Ave.
P. O. Box 26732
Tucson, Arizona 85726-6732
(520) 318-8000
FAX: (520) 318-8303

TORRENT KIT PARTS LIST TRANSITION MODULE BLANK DEWAR INTERFACE KIT

Dwg No.: TRNT-EL-02-0XXX Rev: OD
Next Assembly: TRNT-EL-02-XXXX

LTR	DESCRIPTION	ECR	DATE	BY	APPRVD
	INITIAL RELEASE		7-Jul-11	DMS	

Prepared By: Dee Stover
TRNT-EL-02-0 BLANK Dewar Interface kit.xls

NOTES

BLANK DEWAR INTERFACE KIT

DWG #: TRNT-EL-02-0XXX
7/11/2012

1. Bag blank plate and fasteners, add label with kit #.
2. Bag sizes are approximately the minimum size needed
- 3.
- 4.
- 5.

ITEM	QTY	BINLOC	SEE NOTE	Part Number	MFR	Description
1	1		1,2			Plastic bag 6" x 4" size
2	8		1	HWW F M3 OD7 SS		Washer, Flat, M3 OD 7mm SS
3	8		1	HWW SL M3 OD5.6 SS		Washer, split lock, M3 OD 5.6mm SS
4	8		1	HWS PPH M3x 6 SS		Screw, Phillips Pan Head, M3 x 6mm SS
5	1		1	TRNT-EL-02-1022-001		Blank, Isolation Connector Plate