



NATIONAL OPTICAL ASTRONOMY OBSERVATORY

950 N. Cherry Ave.
P. O. Box 26732
Tucson, Arizona 85726-6732
(520) 318-8000
FAX: (520) 318-8303

TORRENT KIT PARTS LIST TRANSITION MODULE KPNO STD DEWAR CONNECTOR INTERFACE KIT

Dwg No.: TRNT-EL-02-0015 Rev: OD
Next Assembly: TRNT-EL-02-0003
Applicable Documents: TRNT-EL-02-0025

LTR	DESCRIPTION	ECR	DATE	BY	APPRVD
OD	INITIAL RELEASE		7-Jul-11	DMS	

ITEM	QTY	BINLOC	SEE NOTE	Part Number	MFR	Description
1	1		2,4			Plastic bag 3" x 4" size
2	1		4			Plastic bag 6" x 6" size
3						
4						

NOTES:

1. Reference Drawing TRNT-EL-02-0025-002?
2. Bag sizes are approximately the minimum size needed
3. Lubricate threads liberally with isopropyl alcohol before attempting to secure jam nuts, install connectors into holes and secure with jam nuts. On the connectors remove and discard back shell and bayonet collar (save in any NOAO spare parts location)
4. Bag connector interface assembly with already bagged fasteners and label with Kit part number.



